



Encuentre la junta de culata adecuada para los motores TOYOTA de 3.0 litros

**1KD-FTP | 1KD-FTV**


N.º de artículo	Espesor	Número OE	Posición de las muescas	Corresponde al número de muescas en juntas de culata comparables
<b>588.820</b>	0.85 mm	11115-0L020-A0   11115-30030-A0   11115-30031-A0   11115-30032-A0		1
<b>588.830</b>	0.90 mm	11115-0L020-B0   11115-30030-B0   11115-30031-B0   11115-30032-B0		2
<b>354.270</b>	0.95 mm	11115-0L020-C0   11115-30030-C0   11115-30031-C0   11115-30032-C0		3
<b>588.840</b>	1.00 mm	11115-0L020-D0   11115-30030-D0   11115-30031-D0   11115-30032-D0		4
<b>588.850</b>	1.05 mm	11115-0L020-E0   11115-30030-E0   11115-30031-E0   11115-30032-E0		5



**588.820**



**588.840**




**588.830**



**588.850**



**354.270**



**1KD-FTP**



**1KD-FTV**

**ElingKlinger AG | Aftermarket Division**

Max-Eyth-Straße 2 | 72581 Dettingen/Erms | Germany

Phone +49 7123 724-799

service@elring.com | www.elring.com

TS1 03/2026



**Das Original**