



Installation of shaft seal on crankshaft


340.290

Suitable for AUDI | MAN | SEAT | SKODA | VW

Localised leakage may occur at the plastic housing of the radial shaft seal on Euro 6 vehicles of the VW Group equipped with 1.6- or 2.0-liter TDI EA288 engines from model year 2012 onwards.

Elring supplies the radial shaft seal with housing. Installation is performed from the front. To prevent leaks or damage, the following steps must be followed.

- 1.
- 2.
- 3.
- 4.
- 5.
- 6.
- 7.
- 8.
- 9.



340.290



471.501 | 006.553



YouTube

ElringKlinger AG | Aftermarket Division

Max-Eyth-Straße 2 | 72581 Dettingen/Erms | Germany

Phone +49 7123 724-799

service@elring.com | www.elring.com

TS1 02/2026



Das Original