




Trovate la guarnizione della testata giusta per i motori diesel Ford EcoBlue da 2,0 litri


1. Generazione 2015-2018 | Numero di Serie del blocco motore: GK2Q-6010-AC

		#			
0,671-0,720		2 048 131 GK2Q 6051 FA	-	1,30	-
0,721-0,770		2 048 139 GK2Q 6051 GA	-	1,35	-
0,771-0,820		2 048 143 GK2Q 6051 HA	-	1,40	-
0,821-0,870		2 048 150 GK2Q 6051 JA	-	1,45	-
0,871-0,940		2 048 157 GK2Q 6051 KA 2 213 835 HG9Q-6051-AA	806.450	1,50	



Ford EcoBlue

2. Generazione 2018 -> | Numero di Serie del blocco motore: GK2Q-6010-AD

		#			
0,835-0,884	0,885-0,934	2 213 835 HG9Q-6051-AA 2 048 157 GK2Q 6051 KA	806.450	1,50	
0,885-0,934	0,935-0,984	2 213 837 HG9Q-6051-BA	806.460	1,55	
0,935-0,984	0,985-1,034	2 213 839 HG9Q-6051-CA 2 670 021 HG9Q-6051-LA	806.470	1,60	
0,985-1,034	1,035-1,084	2 213 841 HG9Q-6051-DA 2 670 025 HG9Q-6051-MA	806.480	1,65	
1,035-1,084	1,085-1,134	2 213 843 HG9Q-6051-EA 2 670 027 HG9Q-6051-NA	806.490	1,70	
-	-	2 213 845 HG9Q-6051-FA	806.540	1,75	
-	-	2 213 847 HG9Q-6051-GA HG9Q-6051-RA	806.560	1,80	
-	-	2 670 036 HG9Q-6051-SA	-	1,85	-
-	-	HG9Q-6051-TA	-	1,90	-

ElringKlinger AG | Aftermarket Division

Max-Eyth-Straße 2 | D-72581 Dettingen/Erms

Fon +49 7123 724-799 | Fax +49 7123 724-798

service@elring.de | www.elring.com

SI 09/2024



Das Original